


1. Power feed
2. Support structure
3. Fasteners
4. Mounting Plate(s)
5. Profile
6. Diffuser



**1**

\*Flush surface mount

XTI Profile

Suspension Plan

NOTE: Fasteners are **NOT** supplied

\*Note: The Flush Surface mount comes assembled with the XTI profile

**2**

## Determine mounting location

**3**

Position luminaire and mark mounting holes

**4**

Remove luminaire and drill pilot holes for mounting

**5**

Drill clearance hole for \*power feed

\*Note: When using an IP plug, allow for additional diameter of power feed hole

**6**

Connect Luminaire to power supply

**7**

Return luminaire to installation location and fix through mounting brackets

If more information is required please contact your local representative by going to [xerolightingusa.com/contact](http://xerolightingusa.com/contact) or email us at [ussales@xerolighting.com](mailto:ussales@xerolighting.com)